

PART I. TYPICAL ACCEPTABLE SOLDER CONNECTIONS




FIGURE 7



FIGURE 8



FIGURE 9



FIGURE 10



FIGURE 11



FIGURE 12

PART I. TYPICAL ACCEPTABLE SOLDER CONNECTIONS	
<p>FIGURE 7</p> <p>PWB lapped termination; Ribbon lead through the PWB to rectangular pad.</p> <p>MINIMUM ACCEPTABLE</p>	<p>FIGURE 8</p> <p>PWB lapped termination; Ribbon lead through the PWB to rectangular pad.</p> <p>MAXIMUM ACCEPTABLE</p>
<p>FIGURE 9</p> <p>PWB stud termination.</p> <p>MINIMUM ACCEPTABLE</p>	<p>FIGURE 10</p> <p>PWB stud termination.</p> <p>MAXIMUM ACCEPTABLE</p>
<p>FIGURE 11</p> <p>PWB clinched termination; Round lead to circular pad.</p> <p>MINIMUM ACCEPTABLE</p>	<p>FIGURE 12</p> <p>PWB clinched termination; Round lead to circular pad.</p> <p>MAXIMUM ACCEPTABLE</p>